



## UPPER MORELAND POLICE

### **Jason Drive - Speed Study October 2016**

#### ***Initial Complaint:***

A resident reported that vehicles speed at all times of the day on Jason Drive.

#### ***Description of Area:***

Jason Drive is located in the Huntingdon Valley section of Upper Moreland Township. It is a local roadway located within a residential neighborhood in the northeast corner of the Township. Jason Drive is a cul-de-sac off of Shoemaker Road that has sidewalks on both sides of the street. The roadway is wide enough to accommodate on street parking and the speed limit is 25 mph.

#### ***Data Gathering Method:***

Speed/volume counters were placed on the no parking from Gum Pl to here sign near 2001 Jason Drive for a period of seven days.

#### ***Hazardous Factors:***

Evaluating the speed of vehicles, the volume of traffic, and the total number of crashes assists in determining the level of response necessary to address the public safety concern.

The speed of vehicles using this part of Jason Drive indicated that 0.07% of vehicles met the threshold for enforcement. The 85<sup>th</sup> percentile speed for vehicles on this part of Jason Drive is 22.95 mph.

During the study period, 2,823 vehicles traveled on this section of Jason Drive.

Crash reports do not indicate that there is an existing public safety hazard on this section of roadway.

#### ***Analysis:***

At this time, speeding is not an issue on this part of Jason Drive. The average speed is 20.3 mph.

#### ***Response:***

This location does not require any traffic calming measures or enhanced patrol at this time.